

Copper Alloys	Cu	Sn	Pb	Zn	Fe	Ni	P	Al	Mn	Si	Sb	S	Bi	Cr	Impur-ities
<b>Aluminium Bronze</b>															
AB-1	Rem.	0.1	0.05	0.5	1.5-3.5	1		8.5-10.5	1	0.25					0.3
AB-2	Rem.	0.1	0.05	0.5	4-5.5	4-5.5		8.8-10	1.5	0.1					0.3
AB-3	Rem.	0.1	0.03	0.4	0.5-0.7	0.1		6-6.4	0.5	2-2.4					0.8