

Copper Alloys	Cu	Sn	Pb	Zn	Fe	Ni	P	Al	Mn	Si	Sb	Impurities
<b>Gun Metal</b>												
<b>IS:1458-1965</b>												
Gunmetal Class-2	Rem.	5-7	1-3	2-3	0.3		0.05	0.01			0.1	0.6
<b>IS:318-1981</b>												
LTB-1	Rem.	6-8	2.5-3.5	1.5-3	0.3	2		0.01		0.01	0.3	0.7
LTB-2	Rem.	4-6	4-6	4-6	0.35	2		0.01		0.02	0.4	0.8